


Table of Contents

Dallas / Maxim DS18B20 1

Dallas / Maxim DS18B20

- 1-Wire Digital Thermometer
- Measures Temperatures from -55°C to +125°C
- ±0.5°C Accuracy from -10°C to +85°C
- Standby current typically is 3µA
- Unique serial number
- Wires max 200meters

<https://datasheets.maximintegrated.com/en/ds/DS18B20.pdf>



From: <https://wiki.janforman.com/> - wiki.janforman.com

Permanent link: <https://wiki.janforman.com/iot:ds18b20>

Last update: 2017/08/05 11:40

